


BELZONA SEALS LOCAL ROOF PROBLEM

ID: 1139



PROBLEM

Building was being refurbished inside and the roof was leaking in the corner halting the interior work.

APPLICATION SITUATION

Roof of army base building.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflets RPA-1,2 & 7. A fully reinforced Belzona® 3111 system was applied to the corner of the roof where leaks were identified.

BELZONA FACTS

Repair was done in one day and was leak-free by the next morning when a storm came in. The Belzona system is ideal for localized repair, where its excellent adhesion ensures no peel-back for edges.

INDUSTRY

Military

LOCATION

Military Base, Oklahoma

APPLICATION DATE

May, 2008

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Bitumen

PHOTOS

1. Leaking section of roof after washing and drying
2. Belzona 3911 (PSC Conditioner) applied
3. First coat of Belzona 3111 incorporating reinforcing sheet applied
4. Completed roof repair and leak free

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

