

BELZONA SEALS SKYLIGHTS ON JET HANGER

ID: 1140



PROBLEM

The roof of the hanger has 16 skylights and each one leaked. Several earlier attempts to seal skylights proved futile.

APPLICATION SITUATION

The hanger houses NASAs corporate jet. The internals of the hanger are spotless and the leaks presented an embarrassment for the owner. Also in consideration was a banquet to be held inside the hanger within 10 days of our repair.

APPLICATION METHOD

Applied utilizing Belzona Know-How System Leaflet RPA-3. Skylights were pressure washed clean, taped off areas around skylights to include joints and seams, applied Belzona® 3921 and 2 coats of Belzona® 3111 Flexible Membrane with Belzona® 9311 Reinforcing Sheet.

BELZONA FACTS

After several prior attempts to seal leaks with other companies, airport personnel called us to fix the leaks.

INDUSTRY

Buildings & Structures

LOCATION

Private Airport Services, North Alabama
U.S.A.

APPLICATION DATE

October, 2007

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Aluminum

PHOTOS

1. Skylights with runways in background
2. Taped off and ready to coat
3. Belzona 3111 1st coat going on
4. Finished job. No leaks - no problems!

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.