

BELZONA REFURBISHES MILITARY DOG KENNELS

ID: 1142



PROBLEM

An easy to clean, hygienic non slip coating required.

APPLICATION SITUATION

Floors and walls in dog kennels.

APPLICATION METHOD

This application was performed in accordance with Belzona Know-How System Leaflets FPA-3 & TCC-15.

To create a non-slip surface that did not damage paws, different aggregates were tried before settling on a non-standard Belzona one that was found to be ideal. Coves between wall and floor were formed and Belzona® 5111 provided stain resistant finish.

BELZONA FACTS

The Commander tried many different coatings over the years and had not found a suitable coating that stood up to the wear and tear of the dogs. Our Belzona application has been down for 2 years and looks just like new.

INDUSTRY

Buildings & Structures

LOCATION

Military Base, North Alabama

APPLICATION DATE

April 2006

PRODUCTS

Belzona 4111 (Magma Quartz)Belzona 5111 (Ceramic Cladding)Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete and Cinder Block

PHOTOS

1. Prepped and ready to coat
2. Floor and coves covered
3. Almost complete, walls being coated
4. All done! Ready to turn over to the owners

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA®