

BELZONA PEDESTRIAN WALKWAY

ID: 1144



PROBLEM

A hard wearing non-slip surface required to provide a safe route into the hospital

APPLICATION SITUATION

Walkway required for pedestrians crossing from the parking structure to the main door to the Hospital.

APPLICATION METHOD

Application was carried out using a modified version of the Belzona Know-How System Leaflet FPA-8. A slurry mix of Belzona® 4111 tinted white was used.

BELZONA FACTS

Belzona system provided the hard wearing non-slip surface required in this critical area.

System still in excellent condition when inspected 2 years later.

INDUSTRY

Buildings & Structures

LOCATION

Hospital, San Bernardino, California
U.S.A.

APPLICATION DATE

2005

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Asphalt

PHOTOS

1. Walkway marked out and surface prepared
2. Belzona system being applied
3. Application completed
4. Still in excellent condition 2 years later

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.