

OLD APPLICATION MEETS NEW BELZONA APPLICATION

ID: 1174



PROBLEM

The floor gets covered in fuel and water causing a slip hazard. Also the cleaning method began attacking the concrete.

APPLICATION SITUATION

Diesel shop floor and ramps

APPLICATION METHOD

Applications was carried out in accordance with Belzona Know-How System Leaflets FPA-3 & FPA-8.

BELZONA FACTS

The ramps where done over 12 years ago and still in great condition saving time and money spent re-doing them repeatedly with systems. The floor has shown to be a safety benefit that also is easier and faster for crews to clean.

INDUSTRY

Buildings & Structures

LOCATION

Railroad in Saint Paul, Minnesota U.S.A.

APPLICATION DATE

1996 and 2008

PRODUCTS

Belzona 4411 (Granogrip)
Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

1. Preparing the surface
2. Taping off edges
3. Patching holes before coating
4. Old Belzona 4411 on ramps meets new Belzona 5231 on workshop floor

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

