

BELZONA SEALS PACKING FACILITY

ID: 1175



PROBLEM

Roof was leaking through the seams and joints.

APPLICATION SITUATION

Bolted metal roof

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-1.

BELZONA FACTS

The customer was previously using a low cost silicone sealant with poor results allowing continued damage to expensive packing machinery and controls.

INDUSTRY

General Industry

LOCATION

Cement Company, Miami, Florida U.S.A.

APPLICATION DATE

April 2008

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Aluminum

PHOTOS

1. Uncoated seams
2. Belzona 3921 (GSC Conditioner) being applied
3. Seams being coated with Belzona 3111 and reinforced with Belzona 9311
4. Finished application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

