

BELZONA SEALS XYLENE CONTAINMENT AREA

ID: 1191



PROBLEM

EPA suggested the client seal the containment area to prevent leaks of Xylene penetrating into the surrounding ground.

APPLICATION SITUATION

Xylene was leaking from containment area after spills

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15. Area abrasive blasted, damaged concrete repaired with Belzona® 4111 and Belzona® 5811 applied by spray.

BELZONA FACTS

Other coatings had failed. Belzona was used and is still perfect after 7 years.

INDUSTRY

Chemical & Petrochemical

LOCATION

Chemical Plant, North Alabama USA

APPLICATION DATE

2001

PRODUCTS

Belzona 4111 (Magma Quartz) Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. Overall view of the containment area
2. First coat of Belzona 5811 applied
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

