

BELZONA KEEPS AIRPORT SAFE FOR TRAVELLERS

ID: 1196



PROBLEM

Old sealant was coming out of the joints. Steel plates over the joints did not alleviate the safety concerns.

APPLICATION SITUATION

Expansion joints in passenger terminal.

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet FPA-6.

BELZONA FACTS

Joints still in service after 8 years. Excellent adhesion ensures no trip hazard created by failed sealant.

INDUSTRY

Buildings & Structures

LOCATION

Airport, Alabama U.S.A.

APPLICATION DATE

2000

PRODUCTS

Belzona 2221 (MP Fluid Elastomer)

SUBSTRATE

Concrete

PHOTOS

1. The passenger terminal
2. One of the application areas
3. Problem joint in front of escalator
4. Completed Belzona 2221 application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

