

BELZONA REPAIRS PARKING DECK EXPANSION JOINTS

ID: 1197



PROBLEM

Sealant was failing and the concrete was deteriorated on each side of the joint on various levels of the parking deck. Fabricated expansion joints to be installed due to extreme movement.

APPLICATION SITUATION

Expansion joints in car park decks

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-5. Joint nosings were rebuilt with Belzona® 4111 prior to bonding prefabricated expansion joints in with Belzona® 4911.

BELZONA FACTS

Belzona® 4111 was used to repair the concrete due to the quick cure times. Belzona was also used due to superior adhesion in bonding the fabricated expansion joint. Repair has been excellent since 2000.

INDUSTRY

Buildings & Structures

LOCATION

International Airport, Alabama USA

APPLICATION DATE

2000

PRODUCTS

Belzona 4111 (Magma Quartz) Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. View of expansion joint from the floor below
2. Spalled concrete due to water penetration and corrosion of rebar
3. Forming the Belzona 4111 using a 2" x 4" batten
4. Repair after the expansion joint was installed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

