

BELZONA TACKLES PROBLEM WITH MUD FILTER

ID: 12



PROBLEM

Corrosion on the faceplate of the rotary valve.

APPLICATION SITUATION

Faceplate of rotary valve on mud filter

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet VPF-1.

BELZONA FACTS

Conventional repairs would have both been costly and time consuming.

INDUSTRY

Sugar

LOCATION

Sugar Cane Mill in Australia

APPLICATION DATE

1997

PRODUCTS

Belzona 1311 (Ceramic R- Metal)

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Cast Iron

PHOTOS

1. Mud filter.
2. Corroded faceplate of rotary valve.
3. Forming technique being used to apply Belzona Ceramic Metal System.
4. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

