

BELZONA BRIGHTENS UP HOSPITAL LAUNDRY FLOOR

ID: 1205



PROBLEM

The coating that was currently on the floor was worn and causing slip hazards for the employees.

APPLICATION SITUATION

Hospital was looking to replace coating on laundry room floor.

APPLICATION METHOD

Application was carried out using a modified Belzona Know-How System Leaflet FPA-3. The concrete was abraded to remove the existing coating and profile the concrete. Areas masked off and Belzona® 5231 Red and Gray used for demarcation.

BELZONA FACTS

This customer had to have the application done and ready for foot traffic in one weekend. Because of the quick cure times Belzona® 5231 was a perfect fix. One year later the application still looks great.

INDUSTRY

Buildings & Structures

LOCATION

Medical Center, Anniston, Alabama USA

APPLICATION DATE

December 2007

PRODUCTS

Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

1. Floor prior to being prepared
2. Floor after being abraded
3. Belzona 5231 being applied
4. Completed floor

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

