

BELZONA PROTECTS CAUSTIC CONTAINMENT AREA

ID: 1206



PROBLEM

Customers Caustic Containment Area coating had failed and needed a new impervious coating installed.

APPLICATION SITUATION

Caustic Containment Area in water treatment plant.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15. Old coating was removed using high pressure water blasting. Belzona® 5811 was applied to both containment and tank stands.

BELZONA FACTS

Belzona has been used for years in many of Alabama Powers Plants. Customer trusted the product and longevity of previous applications.

INDUSTRY

Power

LOCATION

Power Plant, Alabama USA

APPLICATION DATE

December 2007

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. Containment before old coating removed
2. Containment after old coating removed
3. & 4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

