

BELZONA PROTECTS 98% SULFURIC ACID CONTAINMENT AREA

ID: 1207



PROBLEM

Sulfuric Acid containment area coating had failed and needed re-coating.

APPLICATION SITUATION

98% Sulfuric Acid containment area in water treatment plant.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15. Old coating was removed using high pressure water blasting. Belzona® 4311 was applied to both containment and tank stands.

BELZONA FACTS

Belzona has been used for years in many of Alabama Powers plants. Customer trusted product and longevity of previous applications.

INDUSTRY

Power

LOCATION

Power Plant, Alabama USA

APPLICATION DATE

December 2007

PRODUCTS

Belzona 4311 (Magma CR1)

SUBSTRATE

Concrete

PHOTOS

1. Old coating being removed
2. Belzona 4311 being applied
3. & 4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

