

BELZONA COATS CROSSOVER FLOOR

ID: 1209



PROBLEM

Previous floor coating was not bonded well in many places and needed to be replaced. This is a high traffic interior crosswalk in the plant and needed a non-slip surface.

APPLICATION SITUATION

Replace existing floor coating to high traffic crosswalk.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. Existing coating was removed using a walk behind floor grinder before applying the Belzona® 5231 system. applicators used spiked boots to aid access.

BELZONA FACTS

Belzona® 5231 was chosen because the plant was familiar with many of our products already used in the plant. We were also the best option because of the quick cure time. The application started on Friday evening and floor was prepared, two coats of Belzona® 5231 applied and have them walking on it first thing Monday morning.

INDUSTRY

Buildings & Structures

LOCATION

Car Manufacturing Plant, Alabama USA

APPLICATION DATE

October 2007

PRODUCTS

Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

1. Removing the existing floor coating
2. Applying first coat of Belzona 5231
3. Applying second coat of Belzona 5231
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

