


UNIVERSITY STUDIES BELZONA FLOOR SOLUTION

ID: 1211



PROBLEM

Floor caused trip hazards for employees and previous coatings required annual refurbishment.

APPLICATION SITUATION

Floor areas in service areas/boiler room.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know How System Leaflets FPA-1 & -3.

BELZONA FACTS

This had been a yearly repair and customer was looking for long term solution.

INDUSTRY

Buildings & Structures

LOCATION

University, St Louis, Missouri U.S.A.

APPLICATION DATE

Spring 2008

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

1. Floor before repairs and coating
2. Close up of floor problems
3. Holes in floor repaired with Belzona 4111
4. Floor after coating with Belzona 5231

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

