


BELZONA PROTECTS CONCRETE IN DAIRY

ID: 1213



PROBLEM

Customers concrete flooring was suffering from erosion due to chemical attack. Acidic cleaners are used in vessels and are drained onto the floors.

APPLICATION SITUATION

Repair and protect concrete floors inside of process unit.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3.

BELZONA FACTS

Replacement of original concrete would have required moving all of the vessels and equipment out of the warehouse. This would have been labour intensive and costly. The Belzona solution is far more affordable, will protect the original substrate and is easily maintained for long term service.

INDUSTRY

Buildings & Structures

LOCATION

Dairy plant, South Louisiana U.S.A.

APPLICATION DATE

March 2004

PRODUCTS

Belzona 4311 (Magma CR-1)

SUBSTRATE

Concrete

PHOTOS

1. Original substrate
2. Completed coating around process vessel
3. Complete coating on opposite wall
4. Coating in front of door which endures heavy traffic

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA