


BELZONA "DELIVERS" A SANITARY FLOORING SOLUTION

ID: 1232



PROBLEM

The raw plywood floor with no sealant would be difficult to maintain and keep clean in an area that required a very sanitary environment.

APPLICATION SITUATION

Charitable members of a Texas church were fabricating a portable birthing trailer that would eventually be shipped to Guatemala in an effort to offer a sanitary medical facility for use in an impoverished area that suffered from a high birthing mortality rate.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The walls were taped off approximately 2 inches up the vertical edge, sanded, cleaned then coated with two coats of Belzona® 5811 with minimal Surefoot aggregate added during the first coat process.

BELZONA FACTS

This product was donated through the Belzona Houston Distributorship and one of its Consultants at no cost to the church mission organization. An alternative to 5811 was to purchase an inferior floor coating from a hardware store which would not have had the same trouble-free application or long-lasting result.

INDUSTRY

Buildings & Structures

LOCATION

Church charity organization, Texas

APPLICATION DATE

2006

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Plywood

PHOTOS

1. The portable birthing center
2. Floor prior to coating with walls taped off
3. Finished Belzona 5811 flooring application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

