

BELZONA REPAIRS POWER PLANT COAL BELT

ID: 1233



PROBLEM

After years of use the belt had developed several holes. If the holes were not taken care of it could cause ripping of the belt. prior to Belzona it would take up to a day for previous repair methods.

APPLICATION SITUATION

Primary belt for the power station to get coal from the river to the point of use.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

BELZONA FACTS

This repair took less than an hour from start to finish. Previous repair methods took up to a day. This saved thousands of dollars in down-time.

INDUSTRY

Power

LOCATION

Power Station, Memphis, Tennessee
U.S.A.

APPLICATION DATE

2007

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Damaged belt prior to repair
2. & 3. Repaired belt

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

