

TANK BASE SEALING WITH BELZONA PRODUCT

ID: 1240



PROBLEM

Corrosion at chine angle and water getting under the tank bottom

APPLICATION SITUATION

Oil storage tank.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet GSS-3.

BELZONA FACTS

This is a well proven system for reducing corrosion around tank base where moisture is penetrating beneath tank base.

INDUSTRY

Power

LOCATION

Power Station, Portland, Philadelphia USA

APPLICATION DATE

August 2003

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Steel and concrete

PHOTOS

1. View of the tank
2. Chine angle before application
3. & 4. Finished application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

