

BELZONA ROOF SYSTEM PROVIDES ADDED BENEFITS

ID: 1254



PROBLEM

Minor leaks were causing unsanitary conditions in the kitchen and the HVAC system could not keep up with major temperature and humidity fluctuations causing discoloration in the highly decorative chocolates.

APPLICATION SITUATION

Roof over a kitchen and retail shop.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, -8, -10 and -11.

BELZONA FACTS

The owner remarked about the noticeable difference in temperature and humidity control after just the first coat of Belzona® 3111 was applied. Since the completion of the project, this operation has not had to pursue an HVAC upgrade and the chocolates are once again flawlessly beautiful and delicious.

INDUSTRY

General Industry

LOCATION

Chocolate manufacturer, Kansas City

APPLICATION DATE

March 2008

PRODUCTS

Belzona 3111 (Flexible Membrane) Belzona 4111 (Magma Quartz)

SUBSTRATE

Rolled roofing, mastic, brick and clay tile

PHOTOS

1. Storefront of world renowned chocolate maker
2. View of the roof prior to remediation
3. Application in progress
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

