

BELZONA GETS GRIP ON CONVEYOR SLIPPAGE

ID: 1256



PROBLEM

Pieces of rubber lagging were frequently torn loose due to build up. Excessive wear from moisture, chemical attack and abrasive media was causing belt to slip. Belt would often not track properly due to uneven lagging pads.

APPLICATION SITUATION

Conventional rubber lagged head pulley.

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SHM-12. Belzona® 1321 was blinded to rejection with non-slip aggregate.

BELZONA FACTS

The application was completed in one day for less than half the cost of conventional lagging, which was lasting less than one year! The durable Ceramic S-Metal grip system eliminated belt slippage and protected the pulley from both abrasive and chemical attack. Original rubber lagging system was lasting less than a year.

INDUSTRY

Mining & Quarrying

LOCATION

Quarry, Central Missouri

APPLICATION DATE

January 2009

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Carbon Steel

PHOTOS

Head pulley with damaged rubber lagging
Grit blasted pulley
Belzona non-slip surface
Completed and ready for service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.