

BELZONA PROTECTS OIL GAS SEPARATORS

ID: 127



PROBLEM

Severe deterioration to the internal surfaces of the vessels due to erosion-corrosion and SRB attack.

APPLICATION SITUATION

Two standard designs of test separators used around the world and particularly in the Middle and Far East.

APPLICATION METHOD

The application was carried out in accordance with the Belzona Know-How Leaflet TCC-3

BELZONA FACTS

Belzona® 1391 is now specified by this company for refurbishment of oil/gas separators and also for new separators. The alternative is replacements at \$200,000. Belzona refurbishment saves about \$150,000 per separator. Total worldwide refurbishment programme is going to be worth approximately \$2 million.

INDUSTRY

Oil & Gas

LOCATION

International Equipment Manufacturer to the Oil Industry

APPLICATION DATE

1994

PRODUCTS

Belzona 1391

SUBSTRATE

Steel

PHOTOS

1. General view of separator
2. Application of Belzona 1391 underway in a confined internal space
3. Completed application to all internal surfaces of the separator

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

