

TRANSFORMER LEAK SEALED WITH BELZONA

ID: 1331



PROBLEM

Maintenance department had tried different techniques and products but none of these applications were successful. They did not want to take transformer out of service.

APPLICATION SITUATION

Transformer was leaking oil through the flanges.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-1.

BELZONA FACTS

Plant has tried other products but none of them gave satisfactory results. Belzona solution provided means of sealing the leaks without interruption to supplies.

INDUSTRY

Chemical & Petrochemical

LOCATION

Power Plant, Lithuania

APPLICATION DATE

September 2009

PRODUCTS

Belzona 1161 (Super UW-Metal)

SUBSTRATE

Carbon Steel

PHOTOS

1. Paint and other contamination removed
2. Substrate roughened
3. Belzona 1161 and Reinforcement Tape applied
4. Second layer of Belzona 1161

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

