

BELZONA PROTECTS KORT NOZZLES

ID: 1332



PROBLEM

The Kort nozzles were suffering badly from erosion corrosion.

APPLICATION SITUATION

Pair of kort nozzles on tug boat

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-2.

BELZONA FACTS

Belzona successfully solved this problem and provided long term protection to the nozzles from excessive erosion-corrosion.

INDUSTRY

Marine

LOCATION

Tug boat operator, Egypt

APPLICATION DATE

May 2009

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Mild Steel

PHOTOS

1. The boat in dry dock
2. Grit blasting the nozzles
3. Applying of Belzona 1321
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

