

BELZONA RESCUES KOMATSU LOADER

ID: 1334



PROBLEM

Loader drove over rock and cracked the casing in many areas

APPLICATION SITUATION

Komatsu transmission casing

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-1.

BELZONA FACTS

After trying welding the cracks the oil in this casing continued to leak. That's when Belzona® 1161 came to the rescue. Cost of repair \$1500 vs Komatsu dealer repair over \$20,000. Loader still running after 10 months of operation maintenance free.

INDUSTRY

General Industry

LOCATION

Heavy equipment repair shop, Canada

APPLICATION DATE

November 2008

PRODUCTS

Belzona 1161 (Super UW-Metal)

SUBSTRATE

Mild Steel

PHOTOS

1. Loader
2. Cracked transmission casing
3. Preparation of casing
4. Belzona 1161 after application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

