

BELZONA KEEPS TIRE ROLLING

ID: 1336



PROBLEM

Damage on tire sidewall was exposing steel reinforcement to corrosion

APPLICATION SITUATION

Damaged tire needed fast insitu repair.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-9.

BELZONA FACTS

Belzona repair carried out quickly with tire in place. high adhesion and elasticity of Belzona Elastomer copes with extremes of service and protects tire from further deterioration.

INDUSTRY

Mining & Quarrying

LOCATION

Mine, Canada

APPLICATION DATE

July 2005

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Rubber

PHOTOS

The equipment Crack was veed out and prepared with Belzona roughing brush Belzona 9341 (reinforcement Tape) incorporated for additional strength The completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

