

BELZONA FIXES DRAINAGE PROBLEM

ID: 1345



PROBLEM

Previously installed coating system had failed and was stopping the water or anything else from draining out.

APPLICATION SITUATION

Parking garage storm drain

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The failed coating was ground out to expose clean concrete before application of the Belzona® 5811.

BELZONA FACTS

Customer was very happy with the solution. They now have a drain that gets rid of the water and their worries.

INDUSTRY

Buildings & Structures

LOCATION

Office Building, Ontario Canada

APPLICATION DATE

May, 2009

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. Water and trash not able to escape
2. Removing the old system
3. Grinding back to white concrete
4. Belzona 5811 applied

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

