

BELZONA WATERPROOFS SUNROOM ROOF

ID: 1352



PROBLEM

The roof and flashing on this customers sunroom was allowing water to enter and damage walls and belongings.

APPLICATION SITUATION

A poor roofing job left customer with a leaking sunroom.

APPLICATION METHOD

Using modified Belzona Know-How Systems Leaflet RPA-1, a fully reinforced Belzona® 3111 System was applied.

BELZONA FACTS

When the roof began leaking, the customer looked to the contractor to honor their warranty, but discovered that the contractor was out of business. Belzona provided the solution the customer was looking for and now dry walls and floors keep this customer a Belzona believer.

INDUSTRY

Buildings & Structures

LOCATION

Residential Roof in Ontario

APPLICATION DATE

June, 2009

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Asphalt

PHOTOS

1. Applying Belzona 3911 (Conditioner)
2. Initial application of Belzona 3111 incorporating Reinforcing sheet in 1st Coat
3. & 4 Finished application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

