

BELZONA KEEPS THE BEANS DRY

ID: 1361



PROBLEM

Water ingress between tank and concrete tank base. For several years tar was applied but continually failed.

APPLICATION SITUATION

75 ft. diameter soybean storage bin

APPLICATION METHOD

Application was carried out in accordance with Belzona Know How System Leaflet GSS-3.

BELZONA FACTS

Applying tar around the tank base had proven to be very temporary and unsuccessful. Belzona® 6111 provides excellent corrosion protection to steel wall and Belzona® 3111 provides flexible weatherproof seal. Customer was so pleased with the results of Belzona that 3 more tanks are scheduled for the same treatment.

INDUSTRY

General Industry

LOCATION

Bean processor, Manning, Iowa

APPLICATION DATE

April 2009

PRODUCTS

Belzona 6111 (Liquid Anode)

Belzona 3921 (GSC)

Belzona 3111 (Flexible Membrane)

SUBSTRATE

steel and concrete

PHOTOS

1. Belzona 6111 applied and Belzona 3921 being applied
2. First coat of Belzona 3111 with Reinforcing sheet being applied
3. Completed application
4. Completed application, general view

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

