


BELZONA KITCHEN REPAIR KEEPS THE STUDENTS GOING

ID: 1381



PROBLEM

The tiles were degraded around the stainless steel grate. Following a health and safety inspection, the hygiene of the kitchen was reported so urgent action needed to be taken.

APPLICATION SITUATION

Kitchen serving the restaurant for the University students.

APPLICATION METHOD

The application was carried out following the Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

The Belzona solution offers several advantages to the customer. The excellent adhesion onto different substrates (metal, concrete & tile). The easy to clean surface, proven to be a hygienic solution. It is also resistant to the cleaning liquids used. The Belzona® 4111 is resistant to the pedestrian & trolley traffic in this environment and after 5 years in service, the repair is still in perfect condition.

INDUSTRY

Buildings & Structures

LOCATION

University, France

APPLICATION DATE

June 2004

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Metal, concrete and tiles

PHOTOS

1. Application situation 1 before repair
2. Application situation 2 before repair
3. Application situation 1 after repair
4. Application situation 2 after repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

