

BELZONA SOLVES KITCHEN TRIP HAZARD

ID: 1408



PROBLEM

There is a big transition which was causing a trip hazard as well as limiting cart traffic.

APPLICATION SITUATION

Transition between a rubber floor and a tiled floor.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & -5. The rubber floor was cut out so a slope could be made from the edge of the rubber floor to the tile so that a smooth transition could be created.

BELZONA FACTS

Belzona application offered a long term solution with minimum downtime, quick turnaround, and no VOCs to taint the working environment.

INDUSTRY

Buildings & Structures

LOCATION

Hospital, Charlotte, North Carolina USA

APPLICATION DATE

January, 2009

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Concrete, rubber and tile

PHOTOS

1. Coin shows the transition step
2. Exposed concrete after rubber floor removal.
3. Applying the Belzona 4111
4. The finished job

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

