

BELZONA REPAIRS CASING OF A CEMENT BALL MILL

ID: 1417



PROBLEM

Wear on the casing needed to be rebuilt before the bolting of the new wear plates.

APPLICATION SITUATION

Ball mill used to grind limestone in cement production.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-7.

BELZONA FACTS

Belzona successfully solved this problem in a moderate price.

INDUSTRY

Cement

LOCATION

Cement plant, Egypt

APPLICATION DATE

November 2008

PRODUCTS

Belzona 1121 (Super XL-metal)

SUBSTRATE

Cast iron

PHOTOS

1. General view of the mill.
2. Wear on the shell after dismantling the plates.
3. Application of Belzona 1121.
4. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

