


BELZONA RESTORES COOLING WATER PUMP

ID: 1419



PROBLEM

General corrosion over many years had degraded the operation of the pump.

APPLICATION SITUATION

Main circulating water pump at refinery.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets CEP-1 & -3. All pitting was rebuilt with Belzona® 1111. After the rebuild was complete two coats of Belzona® 1341 applied.

BELZONA FACTS

If left unprotected this pump eventually would have to be replaced. By rebuilding the pump and coating, they are able to preserve their investment and reduce downtime. In addition to these benefits the coating pays for itself through power savings due to increased efficiency imparted by the Belzona coating.

INDUSTRY

Oil & Gas

LOCATION

Refinery, Texas USA

APPLICATION DATE

Fall of 2009

PRODUCTS

Belzona 1111 (Supermetal)
Belzona 1341 (Supermetalgilde)

SUBSTRATE

Carbon Steel

PHOTOS

1. Circulating water pump
2. Damaged suction bell
3. Impeller coated with Belzona 1341 together with rebuilt and coated suction bell
4. Pump discharge coated with Belzona 1341

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

