


BELZONA SAVES FINE PAPER PUMP CASING

ID: 1432



PROBLEM

Badly corroded pump volute could not be put back in service in such bad condition

APPLICATION SITUATION

Pump handling fine pulp.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-5.

BELZONA FACTS

In the past this pump casing would be scrapped and replaced at a cost of R20,000. The Belzona repair cost R4,000, thus saving the customer over R16,000 and providing additional years of protection and service.

INDUSTRY

Pulp & Paper

LOCATION

Papermill, Port Elizabeth, South Africa.

APPLICATION DATE

2009

PRODUCTS

Belzona 1321 (Ceramic S -Metal)

SUBSTRATE

Cast Iron

PHOTOS

1. Corroded Pump Volute before application
2. Volute coated with Belzona 1321
3. The refurbished pump volute ready for service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

