


CONVEYOR ROLLERS ON DREDGER RESTORED WITH BELZONA

ID: 1433



PROBLEM

After dismantling, 17 rollers were revealed to be damaged especially bearings, shaft journal and mounting seats.

APPLICATION SITUATION

Customer was carrying out planned maintenance to their dredger. The conveyor system was dismantled for inspection.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-6, which is also approved by Russian Maritime Register of Shipping.

BELZONA FACTS

The customer decided put into practice to apply composite repairs by our trained distributor. Customer has received quintessence and innovative polymeric repair for their damaged rollers. With the repair customer received high quality of service, guarantee and satisfactory repair.

INDUSTRY

Marine

LOCATION

Fleet Owner, Russia

APPLICATION DATE

September 2009

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. General view of dismantled rollers
2. View of the defects on the rollers
3. & 4. A completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA