

BELZONA RESURFACES BRAKE TEST ROLLERS

ID: 1435



PROBLEM

Worn original anti-slip coating on the brake rollers.

APPLICATION SITUATION

Rollers of the Brekon 131-4S type car brake testing rig.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-12.

BELZONA FACTS

Belzona application avoided the replacement costs and outage of equipment. Between 2007 and 2009, more than 12.000 brake tests have been carried out, which was a very satisfactory result for the client. A Testimonial letter is available from the customer about this application.

INDUSTRY

General Industry

LOCATION

State Road Transport Research Institute, Ukraine

APPLICATION DATE

June 2007

PRODUCTS

Belzona 1821 (Fluid Metal)

Belzona 9211 (Supergrip Aggregate)

SUBSTRATE

Steel

PHOTOS

1. The worn brake test rollers
2. Application of Belzona Grip system
3. Completed application
4. Picture after 2 years in service and more than 12,000 brake tests

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA