

BELZONA REPAIRED STEPS IN GREAT CONDITION AFTER 5 YEARS

ID: 1458



PROBLEM

Due to the steps being on the sea front, over a number of years they had deteriorated where the nosings were damaged and in dangerous condition.

APPLICATION SITUATION

Promenade steps on coast needing repairs.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

The customer had previously carried out localised repairs using alternative concrete repair materials. These products, however, were not effective due to poor adhesion and the nature of the coastal environment. An inspection of the Belzona repairs was carried out after 5 years and there is no signs of deterioration or damage to the step nosings.

INDUSTRY

Buildings & Structures

LOCATION

Local City Council, N.East England

APPLICATION DATE

May 2005

PRODUCTS

Belzona 4131 (Magma Screed)

SUBSTRATE

Concrete

PHOTOS

1. Steps before repair
2. Immediately after repair
3. Steps after 5 years use
4. Close up showing no deterioration after 5 years.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

