

BELZONA REPAIRED STEPS IN GREAT CONDITION AFTER 5 YEARS (2)

ID: 1459



PROBLEM

Due to the promenade steps being on the sea front, over a number of years they had deteriorated where the nosings were damaged and in dangerous condition.

APPLICATION SITUATION

Promenade steps on coast needing repairs.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

The customer had previously carried out localised repairs using alternative concrete repair materials. The products, however, were not effective due to poor adhesion and the nature of the coastal environment. An inspection of the Belzona application was carried out after 5 years and there is no signs of deterioration or damage to nosings whatsoever.

INDUSTRY

Buildings & Structures

LOCATION

Local City Council - N.East England

APPLICATION DATE

May 2005

PRODUCTS

Belzona 4131 (Magma Screed)

SUBSTRATE

Concrete

PHOTOS

1. Steps before repair in May 2005
2. Steps immediately after repair in May 2005
3. Steps five years on in May 2010
4. Further view of steps after five years service.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

