

RESEATING NEW RUDDER BEARING WITH BELZONA

ID: 1478



PROBLEM

Corrosion damage and severe wear led to destruction of the old bearing and irregular form of the housing leading to increased annular space between the new manufactured bearing and the housing.

APPLICATION SITUATION

Installation of new bronze bearing in oversized bearing housing.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-9. The injection was through flexible hose placed into the four channels made in the back of the bearing.

BELZONA FACTS

Belzona saved time and money against expensive machining of the housing and supply of larger bronze bush. No alternative was fast enough to compete. This standard repair procedure eliminates galvanic corrosion and provides long term location of the bearing.

INDUSTRY

Marine

LOCATION

Dockyard, Bulgaria

APPLICATION DATE

June, 2010

PRODUCTS

Belzona 1221 (Super E-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Cast Iron housing & Bronze bearing

PHOTOS

1. Bronze bearing machined and ready to be inserted in to the housing
2. Centralizing of the bearing in progress
3. Bae of bearing sealed with Belzona 1221
4. Finished application after injection of Belzona 1321

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

