

BELZONA REPAIRS LIVE LEAK ON TRANSFORMER

ID: 1490



PROBLEM

Oil leak causing environmental contamination.

APPLICATION SITUATION

Pipework on oil filled transformer.

APPLICATION METHOD

Application was carried in accordance with Belzona Know-How System leaflet VPF-11a. Belzona® 1291 used to firstly seal the live leak. The pipework was then encapsulated to prevent further leakage.

BELZONA FACTS

The costly need to drain down the oil to effect a repair (£8,000) was eradicated, the Belzona repair was carried out in less than 2 hours.

INDUSTRY

Power

LOCATION

Electricity Distribution Company, UK

APPLICATION DATE

2007

PRODUCTS

Belzona 1161 (Super UW Metal)
Belzona 1291 (ES-Metal)

SUBSTRATE

Steel

PHOTOS

1. Leak area
2. Leak stopped with Belzona 1291
3. Application completed with Belzona 1161

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

