

BELZONA SEALS LEAKING OIL PUMP

ID: 1493



PROBLEM

Oil was leaking from several parts of mechanical seal flanges.

APPLICATION SITUATION

Crude oil pump operating at ambient temperature and 0.05 Mpa pressure.

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet VPF-11a. Surface was prepared with an MBX Bristle Blaster and initial leaks were temporarily sealed with Belzona® 1221 before permanent sealing with Belzona® 1161.

BELZONA FACTS

Traditional repairs needed to take the pump out of service. Use of Belzona allowed the repair to be carried out while the pump continued in operation, leading to significant cost savings.

INDUSTRY

Oil & Gas

LOCATION

Oil company, Japan

APPLICATION DATE

January, 2010

PRODUCTS

Belzona 1221 (Super E Metal)
Belzona 1161 (Super UW Metal)

SUBSTRATE

Stainless steel

PHOTOS

1. Seal area before application
2. Surface preparation completed
3. Application of Belzona 1221
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

