

BELZONA STOPS LEAK DRAIN PIPE AND HOT WELL PUMP

ID: 1498



PROBLEM

Leaking drain pipe and hot well pump at Water Treatment Plant

APPLICATION SITUATION

Drain pipe and hot well pump of a condenser

APPLICATION METHOD

The application was carried out in accordance with a modified of Belzona Know-How System Leaflet HEX-9 and CEP-6 . First, Belzona 1291 was used to stop the leak, then Belzona 1161 along with Belzona 9341 covered the area.

BELZONA FACTS

The traditional repair solution is not appropriate and loss a lot of time and cost, but Belzona solution is quick and easy, especially, can help the client reduce downtime and replacement cost.

INDUSTRY

Water / Wastewater

LOCATION

Illinois, USA

APPLICATION DATE

December 2008

PRODUCTS

Belzona 1161 (Super UW Metal)
Belzona 1291 (ES-Metal)
Belzona 9341 (Reinforcing Tape)

SUBSTRATE

Metal Steel

PHOTOS

1. Overview of the large sized hole on drain pipe
2. To seal with Belzona 1161
3. Live leaks of hot well pump
4. Stop leak with Belzona 1291 and Belzona 1161

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

