

# BELZONA SEALS GASOLINE STORAGE TANK

ID: 1499



## PROBLEM

Water was collecting on this large reinforcement seam causing extensive corrosion.

## APPLICATION SITUATION

A large gasoline storage tank

## APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-1. The application was completed from the support equipment (crane).

## BELZONA FACTS

Belzona® 1161 was used due to the difficulty in accessing and removing all condensation in the repair area. The application is in excellent condition until today without any problems.

## INDUSTRY

Chemical & Petrochemical

## LOCATION

Petrochemical plant, Ontario, Canada

## APPLICATION DATE

Summer 2008

## PRODUCTS

Belzona 1161 (Super UW Metal)

## SUBSTRATE

Steel

## PHOTOS

1. Large corrosion area
2. Severity of corrosion clearly evident
3. Use of crane lift to access repair area
4. Completed Application

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured  
under an ISO 9001 Registered  
Quality Management System.

[www.belzona.com](http://www.belzona.com)

