

RUBBER PUMP LINERS REPAIRED WITH BELZONA

ID: 1505



PROBLEM

Slurry product destroys rubber liners in 3 weeks.

APPLICATION SITUATION

Rubber liners in Slurry pump

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SHM-9. Belzona Roughing Brush used to prepare surface before Conditioning then rebuilding with Belzona® 2111.

BELZONA FACTS

The rubber liners coated with Belzona® 2111 are currently lasting 3 times longer than OEM parts. The cost to repair is also lower than a new liner.

INDUSTRY

Mining & Quarrying

LOCATION

Mine, Namibia

APPLICATION DATE

July 2009

PRODUCTS

Belzona 2111 (D&A High-Build Elastomer)

SUBSTRATE

Rubber

PHOTOS

Damaged rubber liner Rubber liner being coated with Belzona 2111 Rubber liner after application of Belzona 2111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

