

SEALING TRANSFORMER OIL VALVES WITH BELZONA

ID: 1518



PROBLEM

Valves were leaking oil due to a defective flange seal.

APPLICATION SITUATION

Oil valves feeding a transformer at substation.

APPLICATION METHOD

The application was carried out according to the Belzona Know-How System Leaflet VPF-12,

BELZONA FACTS

Using Belzona surface tolerant material, the leak was stopped reducing maintenance costs and extending the service life of the equipment. Impact on the environment was also reduced.

INDUSTRY

Power

LOCATION

Electricity distribution, Vitoria, Spain

APPLICATION DATE

December 2009.

PRODUCTS

Belzona 1161 (Super UW-Metal)

SUBSTRATE

Carbon steel and plastic.

PHOTOS

1. General view of the location for the unit
2. Cleaning the application area.
3. Final result after application of Belzona 1161

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

