

DUCT SEALING WITH BELZONA 4211

ID: 153



PROBLEM

Water leakage into the chambers causing cable joints to be submerged and extensive disruptions to telephone lines. Problem is particularly great during the monsoon.

APPLICATION SITUATION

Underground chambers containing cable joints

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet VPF-11b suitably modified.

BELZONA FACTS

"Live" leaks were effectively sealed eliminating major disruption to the local and national communication systems.

INDUSTRY

General Industry

LOCATION

Telecommunications in India

APPLICATION DATE

August 1999

PRODUCTS

Belzona 4211 (Magma-Stop)

SUBSTRATE

Concrete, rubber and PVC

PHOTOS

1. Access to the chambers
2. The cable connections
3. & 4. Application of Belzona 4211 underway

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

