

BELZONA BELT SWAT TEAM

ID: 156



PROBLEM

A small hole under belt tension is expected to get larger and debris was leaking through the belt.

APPLICATION SITUATION

Conveyor belt

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet SHM-11.

BELZONA FACTS

There was less than 1.5 hours from start to finish of the application. Little downtime resulted in significant cost savings to the paper mill.

INDUSTRY

Pulp & Paper

LOCATION

Paper Mill in Jacksonville, Florida

APPLICATION DATE

September 1995

PRODUCTS

Belzona 2311 (SR Elastomer)
Belzona 2911 (Q.D. Conditioner)

SUBSTRATE

Rubber

PHOTOS

1. Belt delivers bark to powerhouse, 24 hours a day, 7 days a week
2. Surface preparation completed using Belzona roughening brush, and Belzona 2911 (Q.D. Conditioner) is applied
3. Hole successfully patched by the happy crew (Belt Swat Team)!

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

