

BELZONA FOOD PROCESSING FLOOR

ID: 157



PROBLEM

The floor was badly deteriorated from constant wear and washings.

APPLICATION SITUATION

Floor

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet FPA-1.

BELZONA FACTS

The customer has been using Belzona® 4000 series products for concrete repairs for the past seven years with excellent results. Despite the fact that a bid from another supplier was \$8000 less, the customer, based on past experience, elected to go with Belzona.

INDUSTRY

General Industry

LOCATION

Food Processing Plant in Minnesota

APPLICATION DATE

August 1995

PRODUCTS

Belzona 4131 (Magma Screed)

Belzona 4111 (Magma Quartz)

Belzona 4151 (Magma Quartz Resins)

SUBSTRATE

Concrete

PHOTOS

1. Severely damaged areas patched with Belzona 4131
2. Application of slurry Belzona 4111/4151 system in progress
3. The completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

