

BELZONA BRIDGES A SLIPPERY PROBLEM

ID: 1570



PROBLEM

During winter when wet and icy conditions occurred, slipping and falls resulted to pedestrians using the bridge.

APPLICATION SITUATION

Footbridge clad in exotic wood (similar to decking)

APPLICATION METHOD

The application was carried out using a modified version of Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

The bridge links the famous Louvre and Orsay Museums and has regular traffic. A test was carried out in 2000 and following its success, the full bridge was treated in 2003 with a total of 19661m of grip system. Its performance can easily be viewed and assessed by all.

INDUSTRY

Buildings & Structures

LOCATION

City of Paris, France

APPLICATION DATE

2000 & 2003

PRODUCTS

Belzona 4411 (Granogrip)

SUBSTRATE

Other

PHOTOS

1. Non-disruptive application in 2000
2. Non-disruptive application in 2000
3. Users in 2005
4. Close up in 2007

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

