


BELZONA PROVEN PROTECTION FOR SEDIMENTATION TANK

ID: 1574



PROBLEM

The tanks suffer from severe corrosion.

APPLICATION SITUATION

Open topped sedimentation tanks used for Ferric sulphate water clarification.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5. The Belzona was applied using Airless spray equipment.

BELZONA FACTS

Since 1998 5 clarifier tanks have been coated for the pharmaceutical producer. Inspections after 10 years had shown that Belzona 5811 performed excellently. This proved a key influencing factor for the customer to choose Belzona again.

INDUSTRY

Buildings & Structures

LOCATION

Pharmaceutical producer, Slovakia

APPLICATION DATE

1998 to September, 2010

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Steel

PHOTOS

1. Tank showing severe corrosion
2. Grit-blasting the tank
3. Setting up the spray equipment
4. Tank after the application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

